

Consumable Item List

| S.NO | ITEM | LOKER NO. | BLOCK | QTY | |
|------|---------------------|-----------|-------|----------------|--|
| 1 | Chisel set | 1612 | E | 1 SET | |
| 2 | Rubber Hammer | 1612 | E | 1 | |
| 3 | Wood Hammer | 1612 | E | 1 | |
| 4 | Ball Pin Hammer | 1612 | E | 2 | |
| 5 | Douwles (1",2") | 1612 | E | 1 and 1/2 pack | |
| 6 | Gloues (yellow) | 610 | B | 5 pair | |
| 7 | cuut proof gloues | 610 | B | 5 pair | |
| 8 | safty gloues | 610 | B | 1 | |
| 9 | HB pencil | 610 | B | 4 | |
| 10 | Ereaser | 610 | B | 1 | |
| 11 | Cottun gloues | 610 | B | 5 Pair | |
| 12 | Fevi col (500 mg) | 1745 | B | 5 Bottle | |
| 13 | Fevicol (200 mg) | 1745 | B | 9 Bottle | |
| 14 | Fevicol (1 kg) | 1745 | B | 2 Bottle | |
| 15 | wd 40 | 1745 | B | 2 | |
| 16 | 15 Propyl Alchohal | 1745 | B | 2 | |
| 17 | 3 M chain Lubricant | 1745 | B | 2 | |
| 18 | D Sholdring Pump | 692 | c | 2 | |
| 19 | Soldring Wire | 692 | c | 9 | |
| 20 | Soldring Paste | 692 | c | 9 | |
| 21 | Iron Stand | 692 | c | 2 | |
| 22 | Lable Tape | 692 | c | 11 | |
| 23 | Masking Tape | 692 | c | 13 | |
| 24 | Wood Polish | 692 | c | 1 | |

| | | | | | |
|----|---------------------------|-----|---|-----------------|--|
| 25 | Insulation Tape | 692 | c | 30 roll (1 box) | |
| 26 | Weight Scale | 692 | c | 1 | |
| 27 | M3 Nuts | 692 | d | 300 Pc | |
| 28 | M3X30 bolts | 692 | D | 100 PC | |
| 29 | m4 nuts | 692 | D | 1990 | |
| 30 | M3X12 Bolts | 692 | D | 200 | |
| 31 | M2x20 Blts | 692 | D | 200 | |
| 32 | M2 X12 bolts | 692 | D | 200 | |
| 33 | m2 nuts | 692 | D | 400 | |
| 34 | M6x1/2" (WOOD SCREW) | 692 | D | 1000 | |
| 35 | M8x20 (PHILIPS HEAD) | 692 | D | 1000 | |
| 36 | M8 NUTS | 692 | D | 996 | |
| 37 | M8 BOLTS | 692 | D | 100 | |
| 38 | M8 x1"(wood screw) | 692 | D | 995 | |
| 39 | M8X10 (philip head) screw | 692 | D | 1000 | |
| 40 | M8x12(PHILIP HEAD) SCREW | 692 | D | 1000 | |
| 41 | M6x1" Wood screw | 692 | D | 1000 | |
| 42 | M6x20(PHILIP HEAD)SCREW | 692 | D | 996 | |
| 43 | M6x12 NUTS | 692 | D | 1000 | |
| 44 | M6x8 SCREW (PHILIP HEAD) | 692 | D | 1000 | |
| 45 | M4x20 SCREW (PHILIP HEAD) | 692 | D | 990 | |
| 46 | M8x1/2" WOOD SCREW | 692 | D | 1000 | |
| 47 | M4x8 SCREW | 692 | D | 2000 | |
| 48 | M4x12 SCREW | 692 | D | 2000 | |
| 49 | WASHERS M4 | 692 | D | 980 | |
| 50 | L BREACKET | 692 | D | 1 PACK | |
| 51 | ANKUR BOLTS | 692 | D | 1 PACK | |
| 52 | NAILS (1" AND 2") | 692 | D | 500,500 | |
| 53 | M6 WASHERS | 692 | D | 1000 | |
| 54 | GLUE GUN | 692 | D | 30 | |

| | | | | | |
|----|----------------------------|-------|------------|----------|--|
| 55 | DOUBLE SIDE TAPE | 692 | C | 10 | |
| 56 | WELDING ELECTRODS | 692 | E | 12 | |
| 57 | FEVIKWIK .5 MG | 692 | E | 12 | |
| 58 | FEVIKWIK 1G | 692 | E | 7 | |
| 59 | FEVIKWIK 2G | 692 | E | 12 | |
| 60 | WELDING GOGGLES | 692 | E | 1 | |
| 61 | DHOTI KAPDA | 692 | E | 1 PACK | |
| 62 | BOX CUTTER | 692 | E | 1 | |
| 63 | TIG ELECTRODS | 1612 | C | 9 | |
| 64 | CUTTING OIL | 1612 | D | 1 BOTTLE | |
| 65 | PERMANENT MARKER | 610 | B | 1 PACK. | |
| 66 | WALL SCREW PLUG (6" ,8: MM | 692 | C | 2 BOX | |
| 67 | Lable Tape | 692 | C | 1 BOX | |
| 68 | STEEL ROD | | LAB | 29 | |
| 69 | WOOD | | STORE ROOM | | |
| 70 | FIRST AD BOX | 1745 | A | 1 | |
| 71 | STENLESS STEEL SHEET | 668 | | 16 | |
| 72 | WHEEL OF CUTT SAW | 1771 | B | 4 | |
| 73 | MANUAL | 1612 | C | | |

PARTS ACCESSORIES

| SNO. | ITEM | LOKER | BLOCK | TOOLS | |
|------|--------------------------------------|-------|-------|-------|--|
| 1 | 4327 HAND POWER ZIG SAW (blade) | 1745 | A | 11 | |
| 2 | TABLE SAW | 1612 | C | 3 | |
| 3 | TIG WELDING | 1745 | A | 1 | |
| 4 | LED LIGHTS | 1745 | A | 2 | |
| 5 | ANGLE GRINDER KEY | 1745 | A | 1 | |
| 7 | soldring heat gun mouth | 1745 | A | 2 | |
| 8 | 3 PC 33B SAFTY TOOLS (SAFTY FOR EAR) | 1771 | B | 5 | |
| 9 | BLACK DECKER TOOL BOX | 1612 | E | 1 | |
| | | | | | |
| | | | | | |
| 8 | MANUAL | 1612 | C | | |

Wall Mounted Tools LIST

| SNO. | ITEM | QTY | | | |
|------|-------------------|-----|--|--|--|
| 1 | SCREW DRIVER | 7 | | | |
| 2 | FEVIKWIK GEL | 4 | | | |
| 3 | WELDING GLASS | 1 | | | |
| 4 | BOSH HOT GUN | 1 | | | |
| 5 | KUPPI | 1 | | | |
| 6 | CHISEL | 3 | | | |
| 7 | TIN CUTTER | 1 | | | |
| 8 | WRENCH | 12 | | | |
| 9 | SPANNERS | 11 | | | |
| 10 | CLAW HAMMER | 2 | | | |
| 11 | CROSS PIN HAMMER | 2 | | | |
| 12 | WOOD HAMMER | 1 | | | |
| 13 | RUBBER HAMMER | 1 | | | |
| 14 | TAPE | 3 | | | |
| 15 | SAFTY GLASS | 1 | | | |
| 16 | CUTTER BOX | 1 | | | |
| 17 | PLIER | 1 | | | |
| 18 | WIRE STRIPPER | 1 | | | |
| 19 | LINE TESTER | 1 | | | |
| 20 | PINCERS | 1 | | | |
| 21 | ALLEN KEY SET | 1 | | | |
| 22 | LABLE MANAGER | 1 | | | |
| 23 | AUGER BITS | 3 | | | |
| 24 | BLACK DECKER 12 V | 1 | | | |
| 25 | LED LIGHT | 1 | | | |

| | | | | | |
|----|-------------------------|---|--|--|--|
| 26 | SCISSOR | 2 | | | |
| 27 | HOT GLUE GUN | 1 | | | |
| 28 | F CLAMP | 2 | | | |
| 29 | MAGNETIC HANDLE | 1 | | | |
| 30 | ICHITAPE | 2 | | | |
| 31 | CABLE CUTTER | 1 | | | |

NON-CONSUMABLE ITEM LIST

| SNO. | ITEM | LOKER NO. | BLOCK | QTY. | USED FOR |
|------|-------------------------------|-----------|-------|-------|---|
| 1 | 4327 HAND POWER ZIGSAW | 1612 | C | 1 | CUUTING FOR WOOD OF ANY TYPE |
| 2 | JS 1602 POWER SHEIR HAND HELD | 1612 | C | 1 | FOR METAL CUTTING |
| 3 | BO 3710 ORBITAL SANDER | 1612 | C | 1 | SANDING FOR WOOD |
| 4 | GRINDER CUTTING WHEEL | 1612 | C | 10 | USED IN ANGLE GRINDER FOR SANDING , WOOD METAL |
| 5 | TWIST DRILL SET | 1612 | C | 9 | USE FOR MAKE A HOLE IN WOOD AND METAL |
| 6 | FLATE DRILL SET | 1612 | D | 1 | USE FOR HOLE IN WOOD |
| 7 | LINE TESTER | 1612 | D | 1 | CHECK VOLTAGE /A.C CURRENT |
| 8 | DIGITAL MULTIMETER | 1612 | C | 1 | CHEKING AC AND DC VOTL .ETC |
| 9 | SOLDRING IRON STAND | 1612 | C | 3 | STAND FOR IRON |
| 10 | GBM 10 RE(DRILL) | 1612 | C | 1 | USE FOR DRILLING WORK |
| 11 | JN 1601 ,NIBBLER | 1612 | C | 1 | CLEAN AND PRECISE WORK KEYSTONE PLATE MATERIAL |
| 12 | FORSTNER DRILL | 1612 | D | 2 | CUTTING ANGLES FOR FLATE BOTTON HOLES |
| 13 | SPANER AND WHRENCH | 1612 | D | 2 | TIGHT AND OPEN BOLTS |
| 14 | TORX SCREW DRIWER SET | 1612 | D | 1 | OPN SCREW , AND CLOSING SCREW |
| 15 | MINI PLIERS SET | 1612 | D | 2 | USE IN AS CONDITION (Example-OPEN/CLOSE BOLTS) |
| 16 | TABLE SAW SAFTY GLASS | 1745 | A | 1 | USE FOR SAFTY FROM TABLE SAW BLADE |
| 17 | VERNIER CALIPERS | 1612 | D | 2 | USE FOR MESURMENT |
| 18 | WIRE STRIPER | 1612 | D | 1 | CUUTING FOR WIRE |
| 19 | ALLEN KEYS (SET) | 1612 | D | 1 | USE FOR OPEN HEXAGONAL BOLTS |
| 20 | SCREW DRIVER SET | 1612 | D | 2 | FOR SCREW OPEN/CLOSE |
| 21 | MINI FYING GLASS | 1612 | D | 1 | FOR MAGNIFYING A IMAGE OF PRODUCT |
| 22 | AUGER BITS | 1612 | D | 3 | ROTATING HELICAL SCREW BLADE/MAKE HOLE IN WOOD |
| 23 | 14 PCS HOLE SAW KIT | 1612 | D | 1 | MAKE HOLE,CUTT,AND SAW |
| 24 | 5M MEASURMENT TAPE/INCHITAPE | 1612 | D | 1 | FOR MEASURING LENTGH AND BREADTH |
| 25 | FORCEPS/CHIMTI | 1612 | D | 2 | USE FOR MINI ITEM CACTHING |
| 26 | TIN CUTTER | 1612 | E | 1 | CUTTING FOR THIN METAL |
| 27 | PINCERS | 1612 | E | 2 | BROKEN /OPEN NAILS OUT FROM WOOD |
| 28 | CABLE CUTTER | 1612 | E | 1 | FOR CUTTING CABLE |
| 29 | HAND SAW (WOOD,METAL) | 610 | B | 1..1 | CUTT FOR WOOD AND METAL |
| 30 | T SQUARE | 610 | B | 2 | MAKE A ANGLE AS 90 DIGREE |
| 31 | FILE | 610 | B | 2 | FOR GRINDING ELEMENTS |
| 32 | F CLAMP | 1745 | A | | FOR CLAPMING |
| 33 | HELPING HAND | 692 | C | 2 BOX | USES FOR IRON |

| | | | | | |
|----|--------------------------|-------|---|----|---|
| 34 | KUPPI | 692 | C | 1 | USE FOR DRIVE OIL IN MACHINE |
| 35 | TABLE STAND/PEIR | 692 | E | | FOR TABLE |
| 36 | HAND SAW BLADE | 610 | B | 3 | USE FOR CUTT METAL |
| 37 | BENCH DRILL(FERM) | LAB | | 1 | MAKE A HOLE |
| 38 | CUTT OF SAW (BOSH) | LAB | | 1 | USE FOR CUTT METAL |
| 39 | MITER SAW (MAKITA) | LAB | | 1 | USE FOR CUTT WOOD |
| 40 | TIG WELDER (KILON) | LAB | | 1 | USE FOR WELDING |
| 41 | ARGON GAS CYLENDER | LAB | | 1 | USE FOR ARGON WLDING |
| 42 | BELT SENDER (FERM) | LAB | | 1 | USE FOR SANDING WOOD,METAL |
| 43 | TABLE SAW (MAKITA) | LAB | | 1 | USE FOR CUTT WOOD |
| 44 | ANGLE GRINDER (MAKITA) | LAB | | 1 | USE FOR GRINDING WOOD ,METAL |
| 45 | BENCH GRINDER (MAKITA) | LAB | | 1 | USE FOR GRINNDING METAL |
| 46 | SOLDRING STATION (QUIK) | LAB | | 1 | USE FOR SOLDRING |
| 50 | PLASTIC BENCH (JCB) | LAB | | 1 | USE FOR CLAMP ANY PARTICALES |
| 51 | SUPRA BINS BLUE (BIG) | STOOR | | 10 | USE FOR SAVING TOOLS AND ITEM |
| 52 | SUPRA BINS BLUE (MEDIUM) | STOOR | | 16 | USE FOR SAVING TOOLS AND ITEM |
| 53 | SUPRA BINBLUE (SMALL) | STOOR | | 9 | USE FOR SAVING TOOLS AND ITEM |
| 54 | SUPRA BIN RED (SMALL) | STOOR | | 20 | USE FOR SAVING TOOLS AND ITEM |
| 55 | CLEANER (BOSH) | STOOR | | 1 | USE FOR CLEANING |
| 56 | DREMEL | LAB | | 1 | Sanding, Buffing and Shaping Materials Cutting,Grinding |
| 57 | WOOD VICE | LAB | | 1 | USE FOR CALMP |
| 58 | METAL VICE | LAB | | 1 | USE FOR CALMP |
| 59 | OPNER CYLENDER | 1745 | A | 2 | USE FOR OPEN A CYLENDER |
| 60 | BLUE POINT(TOOL KIT BOX) | 610 | B | 1 | ALL TOOLS S KIT LIKE SPANNER,WRENCH |
| 61 | DRILL SET(BOSH) | 610 | B | 1 | ALL TOOLS FOR MAKE A HOLE |
| 62 | MANUAL | 1612 | C | | |